



LUCCA

PRECISION COFFEE SCALE




OPERATION MANUAL

FRONT



BACK



SCALE OPERATION

MANUAL MODE (Weigh & Time)

The LUCCA Precision scale is operable in one easy-to-use manual mode.

To turn the scale **ON**, press the **POWER** button once. To turn the scale **OFF**, long-press the **POWER** button for two seconds.

To **TARE** or zero out the scale, place an object on the scale and press the **POWER** button once.

To start the **TIMER**, press the **TIMER** button once. To stop the **TIMER**, press the **TIMER** button once. To **CLEAR** the **TIMER**, long-press the **TIMER** button for two seconds.

SPECIFICATIONS

Power: 3.7V rechargeable battery

Charging cable: USB-C

Weighing plate: tempered glass

LED screen

Weight capacity: 0.3-2000g

Measuring unit: g / ml / oz

Division: 0.1g

UNIT DIMENSIONS

Height: 18.5mm

Width: 104.5mm

Depth: 104.5mm

Weight: 270g

INCLUDED ACCESSORIES

Silicone heat pad

USB-C charging cable

CAUTION

- Do not put any object over 55 degrees Celsius / 131 degrees Fahrenheit on the scale. Use the included silicone heat pad.
- Do not shake or incline the scale. Always weigh on a hard and flat surface for accurate weighing.
- When the scale is overloaded (EEEE), take off the object immediately, or it will damage the sensor.
- Do not weigh with the charging cable plugged in.
- Do not leave an object on the scale for long periods of time
- Do not allow children under the age of 12 to use.
- Do not submerge it in water.
- Store the product in a dry, non-corrosive environment.

